LINE

-Y1-

-Y2-

-Y4-

-Y5-

-Y5 DET-

-Y9-

CONTENTS: As Shown On Sheet 2A Plan View

STATION

228+00.00 - 371+45.89 10+00 - 15+74.66

10+00-16+96.77

10+00 - 15+16.39

10+00 - 15+45.75

10+00 - 16+53.89

10+00 - 19+73.09

DRAWN BY: _ J.E. BEVERLY

SHEET NUMBERS

PLAN PROFILE X-SECTS.

4-15 16-27 31-34

28

28

28

7 29

5

9

-L- STA. 225+00.00 LA =

-LI- STA. 225+00.00 LB

13 28

13A 30

STATE OF NORTH CAROLINA


DEPARTMENT OF TRANSPORTATION

DIVISION OF HIGHWAYS
GEOTECHNICAL UNIT

SUBSURFACE INVESTIGATION INVENTORY


STATE PROJECT__34517.3.7 | I.D. NO._R-2911D |
F.A. PROJECT__STP-70(39) |
COUNTY____ROWAN |
DESCRIPTION US 70 FROM SR 1739 (HILDEBRAND RD.)

TO WEST OF SR 1953 (KEPLEY RD.)



NOTE - THE INFORMATION CONTAINED MEREN IS NOT IMPLIED OR GUARANTEED BY THE N. C. DEPARTMENT OF TRANSPORTATION AS BEING ACCURATE NOR IT IS CONSIDERED TO BE PART OF THE PLANS, SPECIFICATIONS, OR CONTRACT FOR THE PROJECT.

NOTE - BY HAVING REQUESTED THIS INFORMATION THE CONTRACTOR SPECIFICALLY WAIVES ANY CLAMS FOR INCREASED COMPENSATION OR EXTENSION OF TIME BASED ON DIFFERENCES BETWEEN THE CONDITIONS INDICATED HEREIN AND THE ACTUAL CONDITIONS AT THE PROJECT SITE.



34517.3.7

CAUTION NOTICE

STP-70(77)

CONSTR.

THE SUBSURFACE INFORMATION AND THE SUBSURFACE INVESTIGATION ON WHICH IT IS BASED WAS MADE FOR THE PURPOSE OF STUDY, PLANNING AND DESIGN, AND NOT FOR CONSTRUCTION OR PAY PURPOSES. THE VARIOUS FELD BORING LOCS, ROCK CORES, AND SOIL TEST DATA AVAILABLE MAY BE REVIEWED OR INSPECTED IN RALEIGH BY CONTACTING THE N. C. DEPARTMENT OF TRANSPORTATION, GEOTECHNICAL UNIT & 1919 250-4088, NEITHER THE SUBSURFACE PLANS AND REPORTS, NOR THE FIELD BORNING LOOS, ROCK CORES, OR SOIL TEST DATA IS PART OF THE CONTRACT.

GENERAL SOIL AND ROCK STRATA DESCRIPTIONS AND INDICATED BOUNDARIES ARE BASED ON A GEOTECHNICAL INTERPRETATION OF ALL AVALABLE SUBSURFACE DATA AND MAY NOT NECESSARILY REFLECT THE ACTULAL SUBSURFACE CONDITIONS BETWEEN BORNOS OR BETWEEN SAMPLED STRATA WITHIN THE BOREHOLE, THE LABORATORY SAMPLE DATA AND THE IN SITU ON-PLACE) TEST DATA CAN BE RELED ON ONLY TO THE DEGREE OF RELIABILITY INHERENT IN THE STANDARD TEST METHOD. THE OBSERVED WATER LEVELS OR SOIL MOSTURE CONDITIONS INDICATED IN THE SUBSURFACE INVESTIGATIONS ARE AS RECORDED AT THE TIME OF THE INVESTIGATION. THESE WATER LEVELS OR SOIL MOSTURE CONDITIONS MAY VARY CONSIDERABLY WITH TIME ACCORDING TO CLIMATIC CONDITIONS INCLUDING TEMPERATURES, PRECINTATION AND WIND, AS WELL AS OTHER NON-CLIMATIC FACTORS.

THE BIDDER OR CONTRACTOR IS CAUTIONED THAT DETAILS SHOWN ON THE SUBSURFACE PLANS ARE PRELIMINARY ONLY AND IN MANY CASES THE FINAL DESIGN DETAILS ARE DIFFERENT, FOR BIDDING AND CONSTRUCTION PURPOSES, REFER TO THE CONSTRUCTION PLANS AND DOCUMENTS FOR FINAL DESIGN REFORMATION ON THIS PROJECT, THE DEPARTMENT DOES NOT WARRANT OR GUARANTEE THE SUFFICIENCY OR ACCURACY OF THE RIVESTIGATION MADE, NOR THE INTERPRETATIONS MADE OR OPINION OF THE DEPARTMENT AS TO THE THYPE OF MATERIALS AND CONDITIONS TO BE ENCOUNTERED. THE BIDDER OR CONTRACTOR IS CAUTIONED TO MAKE SUCH ROPEPIDENT SUBSURFACE INVESTIGATIONS AS HE DEEMS NECESSARY TO SATISFY HASSELF AS TO CONDITIONS TO BE ENCOUNTERED ON THIS PROJECT. THE CONTRACTOR SHALL HAVE NO CLAIM FOR ADDITIONAL COMPENSATION OR FOR AN EXTENSION OF TIME FOR ANY REASON RESULTING FROM THE ACTUAL CONDITIONS ENCOUNTERED AT THE SITE DIFFERING FROM THOSE NOICATED IN THE SUBSURFACE WE FORMATION.

